SPIC/0-162-79

**21** MAY 1970

HERORANDAM FOR: Assistant Deputy Director for Intelligence

SURJECT

: Security and Safety -- NPIC vs USGS

1. Attached is a copy of a report, prepared by the MPIC security staff, about a small fire which occurred in that area of [ occupied by the U. S. Geological Survey. The report describes the circumstances of the fire and the actions various people took -- and did not take -- when the fire was discovered.

25X1

- 2. This incident is one example of a condition affecting security and safety, which causes me considerable uneasiness but which is resistant to corrective measures. In essence, MPIC and USGS -- because they are separately administered functions occupying compartmented portions of the same building -- are dangerous one to the other.
- 3. This incident illustrates that a fire could happen in the USUS area and affect the NPIC area before an evacuation warning had been given to the MPIC area. Another recent incident illustrated that some degree of such danger to the USGS area exists if the fire were to start in the MPIC area, although I am more confident that our system would, in those circumstances, cause USGS to be evacuated in time.
- 4. The greatest danger to people in either case would be from smoke, not flare. The fact that most of the NPIC area lacks windows increases our concern about the smoke danger, whether a fire occurs in the NPIC area or encroaches upon that area from the USIS offices.
- 5. We are taking every measure within our powers of authority and persuasion to reduce such dangers. But, as long as MPIC and USGS occupy the same structure PPIC will lack security and safety integrity.

25X1

Declass Review by NIMA/DOD

Executive Director National Photographic Interpretation Center

Attachment:

a/s

Distribution: cc: Director of Logistics Director of Socurity

Original & 1 - Addressec

Approved For Release 2004/02/11: CIA-RDP78B05703A060200640012-7 (20 May 70) A 1 - NPIC/TSSG/SSD -2 - NPIC/ODIR NPIC/ODIR:

Excluded from a

### UUNFIDENJIAL

# Approved For Release 2004/02/11 : CIA-RDP78B05703A00020004001247 1370

### FIRE INVESTIGATION

	DATE AND TIME :	6 January 1970, 1040 hours	
<b>.</b>	AREA :	U. S. Geological Survey, Department of Interior, Sixth Floor,	25X <sup>2</sup>
	CAUSE :	Paper ignited in Dennison Copier machine	•
	ESTIMATED DAMAGE:	Cost of replacing machine	,
25X1	INVESTIGATED BY :	Safety Officer	
	SUMMARY		
25X1 25X1	1. On 6 January 1970 at approximately 1040 hours, USSP  who was assigned to the NPIC parking lot post, advised  NPIC Security Officer, of a fire reported in the sixth floor offices of U. S. Geological Survey (USGS). Officer  one from USGS had called him requesting that fire equipment, which was enroute, be directed to the sixth floor USGS center.  immediately departed the NPIC Security Center to open the security gate on the roof of should firemen need to enter the USGS		
2EV1	center by this route.		25X
25X1 25X1 [	2. Messrs NPIC Security Officer, Safety Officers, left the NPIC Security  Center to investigate the source of the fire. USGS employees had already evacuated their offices and were scattered about the parking lot in groups and fire equipment was on the scene. Firemen with respirator equipment were seen using the elevator for entry to the		
25X1	USGS offices. USGS employee, was overheard explaining to firemen that the trouble was in a Dennison copying		
25X1	machine which was on fire. entered the USGS office center along with the firemen to determine whether or not 25		
25X1 25X1	was endangered and if employees should be evacuated. Mr.  later communicated by portable radio with the NPIC Control  Center to advise that the fire had been extinguished and there was		

# CONFIDENTIAL

# Approved For Release 2004/02/11 : CIA-RDP78B05703A000200040012-7

25X1	no need for evacuation of personnel. He said foremen were presently clearing the USGS area with smoke ejector equipment and mopping up the water.	
25X1	3. The fire was reported at 1040 by Chief, USGS, to the guard office by the internal fire alarm pull system. This system when activated transmits a fire pre-signal to the USSP console center where a direct fire response alarm can be triggered by the on-duty guard for fire department assistance. The fire alarm pull box was reset at 1052 by the Navy Yard Fire Chief.	25X
i	GENERAL	
25X1	1. Approximately 120 employees are located in the sixth floor suite of offices maintained by the U. S. Geological Survey Mission, Department of Interior at Chemical analysis of rocks and testing for radioactive characteristics is the primary mission of the USGS facility. Work space limitations and lack of storage facilities create additional hazards on the sixth floor. The Safety Staff at a meeting during July 1969 discussed poor housekeeping in the storage of flammable solvents and open storage of noncompatible and poisonous chemicals with Department of Interior Safety Officers.	25X 25X
25X1 25X1 25X1	concern on whether or not the USGS operation created additional fire hazards to and he advised Safety Officer, that he would assign Department of Interior Safety Officer, to conduct an official survey of the USGS facility	25X 25X
	2. The Safety Staff in making a visual inspection of the room after the fire was extinguished noted five one-gallon jugs of ammonia hydroxide and two gallons of duplicating fluid stored within five feet	

2. The Safety Staff in making a visual inspection of the room after the fire was extinguished noted five one-gallon jugs of ammonia hydroxide and two gallons of duplicating fluid stored within five feet of the burned out copying machine. A fire detection dome was not properly positioned in the reproduction area to immediately give an alarm of fire. The USGS office area is provided with a ventilating system independent of the NPIC complex; therefore, no smoke from the fire was evidenced by NPIC personnel within their respective work areas. Firemen mistakenly started their smoke ejection equipment with the exhusting vent inverted which proceeded to blow smoke back into the USGS office areas. However, once the smoke ejector was properly mounted, the area started to clear.

## CONFIDENTIAL

## Approved For Release 2004/02/11: CIA-RDP78B05703A000200040012-7

3. There are also three other emergency exits available to USGS personnel on the sixth floor. Two emergency roof exits are located at the north and south ends of the USGS area and one east side emergency exit leads to an outside stair ladder.

#### DETAILS OF INVESTIGATION

25X1	Interview:	USGS employee
25X1	1,	stated she had been using the Dennison
	<del>-</del>	was operating on its automatic setting, she
		to answer a fellow employee's question. When
		nachine there was heavy smoke and flame coming
	-	e stated she retained her composure enough to
	-	ig before calling for assistance.
25X1		to assist by removing the inner storm window
	S	er glass from the metal casement window to
		e flexible tubing for the USGS toxic fume venti-
		f the building. The flexible tubing was pinched
		d not properly expel the smoke from the area.
25X1		rely cut on his hand while performing this func-
		was not available for interview inasmuch as
	he was taken to a doc	tor's office for attention.
25X1	2.	meanwhile dialed the emergency telephone
	number listed for the	fire department to report the incident. She then
25X1	called Officer	at the main gate to request that the fire depart-
20/(1	ment be directed to t	he USGS offices. made the initial
	report of this incide	nt to the NPIC Security Office.
0574	3.	,
25X1	·	advised she did not pull the internal fire
	•	se she did not have her glasses on and the pull
		rridor away would not have been visible enough
25X1	for her to function th	
		owledgeable of the emergency procedures set
		ndum from the NPIC Security Staff. Several
		ressed a complete lack of knowledge in having
0.5)///	seen this emergency	
25X1	that	USGS chemist, who was also unavailable
	ior interview, respo	nded and attempted to extinguish the smoldering

Approved For Release 2004/02/11: CIA-RDP78B05703A000200040012-7

3

### CUNTIVENIME.

## Approved For Release 2004/02/11: CIA-RDP78B05703A000200040012-7

25X1	fire with CO <sub>2</sub> fire extinguishers. The fire was extinguished by  a USGS employee, utilizing two 10 lb CO <sub>2</sub> extinguishers.  Firemen used a 1 1/2 inch water hose to saturate and cool the smoldering wires in the machine to prevent a reflash.	
25X1	Interview: USSP	
25X1	Officer said he received an alarm signal on the control console approximately seven minutes after Officer initially reported the fire to Security. Due to the fire alarm circuitry arrangement on the sixth floor there is no way to differentiate between automatic and manual alarms in this area.	25X1
25X1	Interview: Security Duty Officer	
25X1 25X1	stated he received notification of a fire at from the GSA Control Center. The GSA Duty Officer related that fire equipment was enroute to render assistance at	
25X1	called the NPIC Security Office for information but was advised that the fire was in the USGS area and Head-quarters would be contacted when more details on the incident were	
25X1 25X1	known then followed through by notifying the Safety Staff of the incident at	
25X1	Interview: Department of Interior	
) EV4	On Thursday, 8 January 1970, telephoned  Department of Interior, Protection Division. When	25X1
25X1 25X1	queried about the USGS fire, stated he had just heard about the incident from USGS Safety Officer designee,	25X1
25X1	but he had not received any details on what had caused the fire or any relative information. was briefed on facts of the	
	incident which could have caused more severe repercussions if chemicals stored nearby had become involved in the fire.  expressed his concern and stated he was being replaced in his present job some time that week but he would surely follow through with	25X <sub>f</sub> 1
25X1	on the incident. His replacement, who had not been	4
25X1 25X1	named at that time, would be properly briefed on the incident by  before he vacated the job. Furthermore, he advised he had been unable to send Department of Interior Safety	
	Officer, to survey the USGS complex at	25X1

#### CUNTIVEINIAL

### Approved For Release 2004/02/11: CIA-RDP78B05703A000200040012-7

was still stationed in Denver, Colorado. He did recall meeting with the Safety Staff in July 1969 wherein he was apprised of unsafe conditions existing at the USGS center.

Interview:	τ'	JSGS employee
	A toxic fume eje	ed the fire by using two CO <sub>2</sub> ctor, previously constructed by USGS tempt to eject the smoke.

#### CONCLUSION

25X1

25X1

- 1. The fire in the Dennison copier is attributed to a faulty paper feed mechanism which allowed paper to become clogged at the light source where heat subsequently ignited the paper. Flame was transmitted into the electrical wiring of the unit which provided additional fuel to support the fire.
- 2. Containers of duplicating fluid and ammonium hydroxide situated nearby would have created additional hazards for USGS personnel and fire fighting units if the fire had gone unchecked. Duplicating fluid has a low flash point and is rated as a flammable solvent. Ammonium hydroxide (acqua ammonia) has the following characteristics:
  - a. Anhydrous ammonia is a strong irritating chemical to the skin, mucous membrane, respiratory tract and eyes. Direct exposure by contact can cause severe burns.
  - b. Although fire and explosion hazards are not great, the gas is flammable in high concentrations, particularly in the presence of combustible material or oxygen and oil. When thus confined, explosions may follow particularly at elevated temperatures and high pressures.
  - c. Even weak solutions of ammonia cause hazards in three ways: first, by the inhalation of gaseous ammonia; second, by eye or skin contact;

## CONFIDENTIAL

## Approved For Release 2004/02/11 : CIA-RDP78B05703A000200040012-7

and third, by oral intake. The degree of danger in each case is proportional to the strength of the ammonium hydroxide solution.

- 3. NPIC emergency personnel were belatedly notified of the fire because USGS employees felt they could adequately extinguish the fire. The fire department was called to expel the intense smoke and eliminate a possible reflash of fire within the machine. USGS employees were negligent in delaying activation of the building's manual fire alarm.
- 4. The USGS toxic fume ventilator was inadequate in expelling smoke from the area. This particular unit is not a smoke ejector as it was custom built by USGS to ventilate toxic chemical fumes.
- 5. The roof emergency exits were open and could have been used for bringing the firemen into the area should the USGS stairwell and elevator from the ground floor level have been inoperative.

### RECOMMENDATIONS

- 1. It is recommended that GSA arrange for a survey of the present USGS fire detection system to establish that each area is properly covered.
- 2. It is also recommended that GSA arrange for a survey of all flammable solvents and dangerous chemicals to insure they are stored in accordance with safety standards.
- 3. It is recommended that the present toxic fume ventilator be supplemented with newer equipment to provide a more positive exhausting of smoke or dangerous chemical fumes from the USGS laboratories in case of accidents dealing with these agents.